



I commenced Survey of Section
Town North,
Range West.

County Surveyor.

E.

S.

COURSE.	DISTANCE.	REMARKS.
May 10 1886 North	40.20 81.19	Surveyed for Henry H. Bullerman in section 23 Town 7 Range 6 From S E sec 23 E $\frac{1}{4}$ original ground worn Hickory $4^{\circ} 5'$ still standing but dead orig mark plain
West	80.21	From NE 23 $4^{\circ} 2'$
West	80.04	From E $\frac{1}{4}$ NE 23 W $\frac{1}{4}$ NW $8^{\circ} 45'$
		H. M. Parker C.S.

May trustee for Road in	1886	Surveyed for John Fitzgerald Jr in section 23 Town 6 Range 7 From S $\frac{1}{4}$ sec 8 Town 6 Range 7 $3^{\circ} 5'$
North	82.79	From S $\frac{1}{4}$ sec 8 Town 6 Range 7 $3^{\circ} 5'$
West	82.46 158.86	From S E sec 32-7-7 remains of both trees found also Br Oak co 886 E $7^{\circ} 45'$ NE sec 5- NW sec 6-6-7 4°
North	41.21	From S sec 3- found corner both trees mark found in Hickory
East	41.34	From W $\frac{1}{4}$ sec 5- center
North	40.78 center	E $\frac{1}{4}$ sec 5- From S $\frac{1}{4}$ sec 5- *7.34 dyd N $3^{\circ} 45'$ 76.34 $3^{\circ} 45'$

Corners Established.	Monument.	Bearing Trees.	Diameter in Inches.	Course.	Links Distant.
T 7 R 6					
cen NW 23	stone	Beach Oak	8	S 42 $\frac{1}{2}$ E	63
NE 23	stone	Gum	12	S 49 N	92
T 6 R 7					
W $\frac{1}{4}$ sec 5	stone	Maple	3	S 62 E	5-2
center sec 5	stone	W Oak		S 59 $\frac{1}{2}$ W	47
E $\frac{1}{4}$ sec 5	stone	Maple	12	S 48 $\frac{1}{2}$ E	32
				H. M. Parker C.S.	
T 7 R 7					
Sec 32		Burr Oak	10	S 86 E	74 $\frac{1}{2}$
		corner sec 4 sec 15		W	821
				H. M. Parker C.S.	